

INFANT SCALE GRAVITY COMPENSATION

1. While pressing the lb/kg key press the on zero key.
2. Display will read F1
3. Press on zero key until it reads F3
4. Press the lb/kg key. Display may read for example .004
5. Display should now be set to 0.00. To change numbers to 0.00 use the on zero key to increase value and the off key to decrease the value.
6. Press the lb/kg key. Display will return to F1.
7. Press the off key.
8. Check with certified weight.

* For technical support call **888-386-8225**

